



**EMMYWATCH**  
VINTAGE RESTORATIONS



Record 103 Movement Parts (1)

*Compiled by EmmyWatch - <https://www.emmywatch.com>*

RECORD WATCH Co. S. A.

PIÈCES DE RECHANGE — ERSATZTEILE  
 EXCHANGE PARTS — PIEZAS DE REPUESTO

Cal. 8  $\frac{3}{4}$  " rond N° 103



RECORD WATCH

VINTAGE RESTORATIONS

1701	1702	1703	1704	1705	1706	1707	1708	1709		
1710	1711	1712	1713	1714	1715	1716				
1717	1717 a	1717 b	1718	1719	1720	1721	1722	1722 a		
1722 b	1723	1723 a	1723 b	1724	1725	1726	1727	1728		
1729	1730	1731	1732	1733	1734	1735	1736	1737	1738	
1739	1740	1741	1742	1743	1744	1745	1746	1747	1748	1749