



EMMYWATCH
VINTAGE RESTORATIONS

Record 223,224 Movement Parts (1)



Compiled by EmmyWatch - <https://www.emmywatch.com>

RECORD WATCH Co. S. A.

PIÈCES DE RECHANGE — ERSATZTEILE
 EXCHANGE PARTS — PIĘZAS DE REPUESTO

Cal. 16''' N° 223 - 224

(Ep. 4,70 mm. = 25/12)



EMMYWATCH

